

Las Vegas Campus Transition and Environmental Due Diligence Process, Pa
Areas of Selective Demolition, May 11, 2015

Room	Inaccessible Item	Covering	Notes
EAX 3	1 wall-inset acid waste line inlet	Wall	
EAX 3	1 floor drain	Tile / Mastic	Suspected underlying ACM.
EAX 3	1 floor drain	Tile / Mastic	Suspected underlying ACM.
QAL 8	1 wall-inset acid waste line inlet	Wall	
QAL 10	1 wall-inset acid waste line inlet	Wall	
QAL 11	1 wall-inset acid waste line inlet	Wall	
QAL 18	1 cleanout	Ceramic Tile	
QAL 20	1 floor drain	Epoxy flooring	
QAL 21	1 floor drain	Rolled flooring	
QAL 21	1 floor drain	Rolled flooring	
QAL 22	1 floor drain	Epoxy flooring	
QAL 22	1 cleanout	Epoxy flooring	
QAL 25	1 floor drain	Epoxy flooring	Suspected underlying ACM.
QAL 25	1 Cleanout	Wall behind Casework	
QAL 31	1 cleanout	Wall	
QAL 32	1 cleanout	Epoxy film / Paint	
QAL 42.1	1 floor drain	Underneath Walk-in Cooler	May have been backfilled with concrete.
QAL 42.1	1 cleanout	Underneath Walk-in Cooler	May have been backfilled with concrete.
QAL 42.1	1 floor drain	Epoxy flooring	May have been backfilled with concrete.
QAL 45.1	1 floor drain	Tile / Mastic	Wall may have been built over the drain.
POS 10	1 cleanout	Concrete	
POS 10	1 floor drains	Concrete	
POS 10	1 floor drains	Concrete	
POS 12.1	1 wall cleanout	Stud in wall	
POS 12.3	1 cleanout	Ceramic Tile	Potential ACM.